



SWS18R

Strata Red Welding Screen

1.8 x 1.8m




Assembly & Parts List

www.strata.co.nz



SWS18R

Strata SWS18R Assembly Instructions



Parts List

1.



Horizontal Tube
x4

2.



Vertical Tube
x4

3.




Top Corner
x2

4.



Bottom Corner
x2

5.




Foot
x2

6.




Connector
x4

7.



Plastic Ties
1pk

8.



Welding Screen
x1




SWS18R

Spare Parts:

SKU	Description
SWC18R	1.8x1.8M Replacement Curtain

Possible Configurations





www.strata.co.nz